



www.nr.utah.gov

Michael O. Leavitt Governor

Robert L. Morgan Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY

August 19, 2003

CERTIFIED RETURN RECEIPT 7099 3400 0016 8896 3625

Mr. John Hewitt Interstate Brick Company 9780 South 5200 West West Jordan, Utah 84088

Re: <u>Five-Year Review of Reclamation Surety Estimate, Interstate Brick Company, Jim Gay Mine, M/049/005</u>, Utah County, Utah

Dear Mr. Hewitt:

The Division is performing the periodic review of reclamation surety estimates to verify their accuracy and make adjustments for escalation and any site modifications that could result in a change of the surety amount presently being held for the site. Division policy requires that surety estimates being held by the State include a five year escalation and be reviewed every five years.

The reclamation surety for Interstate Brick Company's Jim Gay Mine is due for review as of 2003. To assist us in this review, we request an updated map of your site showing current surface facilities and disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or



Page 2 John Hewitt M/049/005 August 19, 2003

shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than October 20, 2003. If you are unable to provide this information in this time frame, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in our surety estimate review. If you have any questions concerning this letter, please contact Doug Jensen at (801) 538-5382.

Sincerely,

Permit Supervisor

Minerals Regulatory Program

jb cc:

Cheryl Martinez, BLM, Salt Lake FO Doug Jensen, DOGM

O:\M049-Utah\M049005-JimGayMine\Final\5yrrev-08192003.doc